

July 23, 2003

Mr. Charence Chang General Manager Crown Capital Enterprise Ltd. B5, Centre Point 181 – 185 Gloucester Road Wanchai, Hong Kong

## To Whom It May Concern:

Echelon Industries, Inc. has conducted a series of evaluations to confirm that the use of RejuvaSeal® can be undertaken safely and that the use of the product will not contaminate ground water.

RejuvaSeal® contains hydrocarbons and like all organic products it may be handled correctly and in accordance with the manufacturer's instructions. Recommendations contained in the MSDS must be followed. Simple precaution such as the use of eye glasses and sun screen lotion can significantly reduce the inherent issue.

RejuvaSeal® has been evaluated for compliant; with Occupational Safety and Health Administration (OSHA) in title 29 of Security of federal Regulations. The analysis was conducted under the direction of a Certified Industrial Hygienist. Employees engaged in the application of the product were outfitted with air monitors to measure the eight (8) hour work shift is confirm compliance within the time-weighted average (TWA) exposures to specified airbythe contaminants. Additional collectors were placed around the equipment used to deliver and apply the product and an area surrounding the application site. The samples were collected and analyzed in accordance with National Institute for Occupational Safety and Health (NIOSH) and/or OSHA methods for the specified contaminants. RejuvaSeal® passed all industrial hygiene air monitoring tests with the average sample measuring less than 10% of the permissible level..

The impact upon ground water contamination was also studied at a site where over 1,000,000 square yards of asphalt was treated with RejuvaSeal<sup>®</sup>. Analysis of dust from winter sweeping, tests for polyaromatic hydrocarbons, and both distilled water and acid leach testing were carried out. Results of this extensive testing have shown no significant exceedances of applicable environmental criteria (CCME), particularly when treated and untreated areas are compared.

If further information is required please advise the undersigned.

Sincerely,

Wm. L. Yandemark

President

Echelon Industries, Inc. • 2557 Glenn Drive • Canyon Lake, Texas, 78133 USA TEL (830) 899-8527 • FAX (830) 899-8541 • Internet: www.echelon industries.com